JOHN AND MARY FELDERMAN FARM, WORKSHOP Northeast Corner of County Road 56 and County Road T Clarkville Vicinity Yuma County: Colorado

HABS NO. CO-129-E HABS COLO 63-CLK.V<sub>j</sub> 1E-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Building Survey National Park Service Department of the Interior Denver, Colorado 80225-0287

HABS COLO 63-CLK.V, 1E-

HABS NO. CO-129-E

## HISTORIC AMERICAN BUILDING SURVEY

# JOHN AND MARY FELDERMAN FARM WORKSHOP

Location: Southwest 1/4 of the Southwest 1/4 of Section 22, Township 5 North, Range 46

West, Sixth Prime Meridian. Yuma County, Colorado. North of the intersection

of County Road 56 and County Road S, vicinity of Clarkville, Colorado.

Present Owner: Farmers Home Administration, U.S. Department of Agriculture

Present Occupant: Vacant

Present Use: None

John and Mary Felderman Farm,
Workshop
HABS No. CO-129-E
(Page \$\frac{1}{2})

#### Workshop

### Exterior

The workshop is a one story building of 2x4 wood frame construction with a gable roof. The foundation is cast-in-place concrete. There is one entry door (west side) and a window opening (west side). The roof is of planks covered with wood shingles. The siding is board and batten with milled battens. The building dates to the 1910s. Immediately to the east is the equipment shed (HABS CO-129-F). The two are connected via a breezeway. The old door opening in the east wall of the workshop is permanently nailed in an open position and a gabled roof passageway links it to the equipment shed, forming a breezeway. The breezeway was added when the equipment shed was added in the 1970s.

### Interior

The interior of the building has a concrete slab floor. In the building there is a modern, oil-fired forge and blacksmithing area. This portion of the building's interior is finished with modern, wallpapered paneling and an asbestos-cement panel behind the forge. There are no ceiling treatments, rather there is exposed framing. The flooring is the concrete slab that also serves as the building's foundation.

#### Existing Condition

The building is in good condition at the present time.